#### **SUMMARY**

1234 Main Street Somerville TN 38068 Buyer Name 10/13/2022 9:00AM



Summary Text (enter here)





# 2.2.1 Flashing KICKOUT FLASHING NOT PROPERLY INSTALLED

WEST Recommendation Contact a qualified professional.





9.7.1 AFCIs

#### **MISSING AFCI**



I observed indications that an AFCI is missing in an area that is required to keep the house safe.

Recommendation Contact a qualified electrical contractor.



11.2.1 Sinks, Tubs & Showers

#### **LOOSE FIXTURE**



I observed indications that the fixture is loose. Not secure. Not installed properly. Loose.

Recommendation

Contact a qualified plumbing contractor.



### 11.4.1 GFCI & Electric in Bathroom GFCI NOT TESTING AS FUNCTIONAL



**GUEST BATHROOM** 

I observed a defect at the GFCI in the bathroom. It was not testing properly. Not functioning.

Recommendation Contact a qualified electrical contractor.



## 14.3.1 Garage Vehicle Door Opener MANUAL RELEASE NOT RED



I observed that the manual release handle of the garage door opener was not colored red so that it can be seen easily. Defect.

Recommendation Contact a qualified garage door contractor.



## 14.3.2 Garage Vehicle Door Opener MANUAL RELEASE NOT ACCESSIBLE



I observed that the handle of the manual release was not easily accessible and more than 6 feet above the garage floor. Defect.

Recommendation Contact a qualified garage door contractor.

